

1998 HAWKER 800XP



Asking Price: 3,200,000
Airframe Total Time: 8730 **Landings:** 5700
Passengers: 8
Engine Model: TFE-731-5BR-1H
Engine Total Time: 8200 8100
Time Between Overhaul: 4200 4200
Long Range Navigation: Dual Honeywell NZ-2000 w/dual GPS
Avionics: Dual Honeywell DFZ-800 IFCS /
Altimeter: Dual Honeywell BA-141
Transponder: Dual Honeywell AZ-850 **TCAS:** Honeywell TCAS-2000
EFIS: Honeywell 5-tube **Altimeter:** Dual Honeywell BA-141
F/DIR: Dual Honeywell DFZ-800 IFCS
AP: Honeywell DFZ-800 IFCS
Radar: Honeywell Primus 880 **Stormscope:** Yes
Comms: Dual Honeywell RCZ-851 w/8.33
Navs: Dual Honeywell RNZ-850
DME: Dual Honeywell RNZ-850
Hi Freq: Dual KHF-950 w/Coltech SELCAL **ADF:** Dual Honeywell RNZ-850
CVR/FDR: Universal CVR-80B
APU: Honeywell GTCP36-150W

Exterior

Colors

White w/carmel, twilight blue & vendetta red

Interior

Accessories

Dual 110-volt AC outlets

Business Equipment

Dual fax outlets

Entertainment Equipment

Airshow 400, audio & video equipment

Refreshment Equipment

Forward refreshment center w/hot liquid container, ice storage & microwave

Carpet

Fawn carpeting

Headliner

Vanilla fabric headliner

Seating

Pecan leather seating, dual forward clubs, new aft RS 2-place couch opposite aft club

Equipment

Lights

Pulse safety

General

Thrust reversers, Concorde lead acid battery, long range oxygen

Addl Cockpit Equipment

General

AlliedSignal GPWS, AirCell ST-3100 SATCOM w/dual handsets, dual Honeywell AZ-850 audio panels, Baker passenger briefing, dual Davtron digital clocks

Exterior

General

Exterior is new as reported 02/01/08

Maintenance

Inspection

RVSM compliant.